Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: HART 1-11H

Field Name: TEMPLE Well File #: 29150

Date Incident:7/12/2016Time Incident:09:30Facility ID Number:County:WILLIAMSTwp: 158Rng: 96Sec: 11Qtr:

Location Description:

Submitted By: Timothy Ilse Received By:

Contact Person: Ben Tarap

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	15	Barrels	15	Barrels	15	barrels	
Brine	15	Barrels	15	Barrels	15	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 9/15/2016 Clean Up Concluded: 7/14/2016

Risk Evaluation:

None

Areal Extent:

Approximately 400 ft. by 65 ft. area onsite.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

All visibly contaminated material was removed and will be replaced with clean fill.

Wastes Disposal Location: R360 Disposal

Agencies Involved: Called John Rumppe @ 6:40 on 7/12/2016

Updates

Date: 7/13/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained on location. NDIC takes oversight.